

Huws Gray (Trusses Plant)
(Unit 8)
Llandegai Industrial Estate
Llandegai
Bangor
Gwynedd
LL57 4YH

900004

Phone: 01248 750 160

User Ref: NL

Date and Time, Zone and Restore Time

Event ,Actions Taken, Completion Time and Operator

03/11/2025 09:53:26	8001 11/03 09:53	Fire Alarm	KO3	03/11/2025 09:56:06
03/11/2025 09:53:26	Fire Alarm (GPRS) A:1 Z:8001 Fire Alarm Channel 1 Alarm			
03/11/2025 09:54:21	Action Started - K3 Gethin Jones (Mobile)			SEB
03/11/2025 09:55:38	Call recording			SEB
03/11/2025 09:55:41	Action in progress: Contact answered - KO3 Gethin Jones (Mobile)			SEB
03/11/2025 09:55:50	Engineer on Site			SEB
03/11/2025 09:55:50	Outcome : Contact has taken responsibility for this alarm - KO3 Gethin Jones (Mobile)			SEB
03/11/2025 09:56:06	Engineer on Site			SEB
03/11/2025 09:56:06	Resolution code (Opr) - Company Related			SEB
03/11/2025 09:56:06	Operator closed (Opr)			SEB

Cause of above Fire Alarm: Unassigend Cause

10/11/2025 15:16:43	8001 11/10 15:18	Fire Alarm	SO1	10/11/2025 15:17:49
----------------------------	-------------------------	-------------------	------------	----------------------------

Actions Legend: P = Police, K = Keyholder Group, S = Site, A = Special Action, F = Fire, G = Gen Agency, I = Installer, M = Medical

10/11/2025 15:16:43	Fire Alarm (GPRS) A:1 Z:8001 Fire Alarm Channel 1 Alarm	
10/11/2025 15:16:56	Action Started - S1 Huws Gray Bangor (Unit 13) (Home)	IND
10/11/2025 15:17:10	C:1 Front Left	
10/11/2025 15:17:12	C:2 Front Left Side	
10/11/2025 15:17:15	C:3 Rear Left SWid	
10/11/2025 15:17:20	C:4 Rear Left	
10/11/2025 15:17:43	C:5 Rear Right	
10/11/2025 15:17:36	Action in progress: Contact answered - SO1 Huws Gray Bangor (Unit 13) (Home)	IND
10/11/2025 15:17:42	Cust Ref: Keyholder Informed	IND
10/11/2025 15:17:42	Outcome : Contact has taken responsibility for this alarm - SO1 Huws Gray Bangor (Unit 13) (Home)	IND
10/11/2025 15:17:49	Keyholder Informed	IND
10/11/2025 15:17:49	Resolution code (Opr) - Operator/Customer Related	IND
10/11/2025 15:17:49	Operator closed (Opr)	IND

Cause of above Fire Alarm: Unassigend Cause
